









DETAIL A:

A tap has to be inserted into drainig hole



DETAIL A:  
1:1



|   |                |                                                                                                                                                               |          |         |
|---|----------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|---------|
| 1 | D              | Na ribsi se dopolni opombo za ležanje, doda se: primerni za -4,0°C do +14,0°C. Spremeni se verzija z AC v AD. Ribsa v Windchillu je skladna z ribso v arhivu. | 06.05.13 | Jure L. |
| 1 | ST sprejeto    | Verzija                                                                                                                                                       | Datum:   |         |
| 1 | Opis spremembe | Verzija                                                                                                                                                       | Dobro!   |         |
| 1 | Opis spremembe | Verzija                                                                                                                                                       | Dobro!   |         |

|                                        |  |                                    |  |
|----------------------------------------|--|------------------------------------|--|
| VENTILATOR                             |  | R11R-40LPS-4M-5756                 |  |
| NE TOLERANJE NERE<br>UNTOLERANCED DIM. |  | ISO 2768-m                         |  |
| D.2                                    |  | POVRŠINSKA OBD.<br>SURFACE TEXTURE |  |
| MATERIAL                               |  | MATERIAL                           |  |
| KOD A:<br>CODE                         |  | 0311-4-0329<br>0311-4-0329         |  |
| VERZIJA ARTIKLA:<br>REVISION ARTICLE:  |  | AD                                 |  |
| LST.<br>SHEET:                         |  | 1                                  |  |
| DOD.<br>OF:                            |  | 1                                  |  |

Opomba:

- ventilator z zatesnjenimi ležaji, primerni za  $-40^{\circ}\text{C}$  do  $+140^{\circ}\text{C}$
- fan with sealed bearings, suitable from  $-40^{\circ}\text{C}$  to  $+140^{\circ}\text{C}$
- navodilo za kontrolo ventilatorja 0301-1-4660
- checking instruction 0301-1-4660

**HEINZ** **FOR NORDICOLD** **CE** DATE  
MADE IN SLOVENIA 03/11-4-0329  
RTIR-40/150S-4M-5756  
1~230V 50/60Hz 200/270W 0,9/1,2A 1360/1560RPM  
MAX.AMB:50/60° C IP54 INS.CL:155 C=10U/4.50V  
TH.PROT. ROT.   
ErP: Effes=29,5% (A,static) N39,6

**HEINZ** **FOR NORDICOLD** **CE** DATE  
MADE IN SLOVENIA 03/11-4-0329  
RTIR-40/150S-4M-5756  
1~230V 50/60Hz 200/270W 0,9/1,2A 1360/1560RPM  
MAX.AMB:50/60° C IP54 INS.CL:155 C=10U/4.50V  
TH.PROT. ROT.   
ErP: Effes=29,5% (A,static) N39,6

ErP: Effes=29,5% (A,static) N=39,6